



Under the above circumstances the Karnataka Fire & Emergency Services Department is issuing the 'Fire Safety Compliance Certificate' to 'The Chitradurga Don Bosco society, 'Don Bosco School (CBSE)', low rise educational building situated at "Khatha No.6605, P.B.No.64 and NH-4 Road, Kelagote, Chitradurga City 577 501".

With reference cited (2) above, the management of 'The Chitradurga Don Bosco society, 'Don Bosco School (CBSE)', had requested to issue the Fire Safety Compliance certificate from our department. In this regard the above addressed educational building was inspected by District Fire Officer, Chitradurga Fire Station, Chitradurga. On 24/11/2025 and submitted the report fulfilled the fire fighting systems and found the firefighting systems are in good working condition during inspection and recommended to issue the Fire Safety Compliance Certificate.

With reference to the above cited subject, as per reference (1), A Conditional Fire Safety Recommendation was issued from this office to the low rise educational building with comprising of ground and 03 upper floors with the height of 16.20 Mtrs. at "The Chitradurga Don Bosco society, 'Don Bosco School (CBSE)'" at "Khatha No.6605, P.B.No.64 and NH-4 Road, Kelagote, Chitradurga City - 577 501". With a condition to fulfill the recommendations and compliance the same within 3 months.

i@

- Ref:-**
- 1) This office FSR No. 25/FSR/RFO/RFO/2025, dated. 14/11/2025.
 - 2) Your request letter dated 15/11/2025.
 - 3) Inspection Report No. 02/College/DFO/CTA/2025, dated. 28/11/2025.

Sub:- Issue of 'Fire Safety Compliance Certificate' with respect of fire prevention, fire fighting and evacuation measures maintained / required at "The Chitradurga Don Bosco society, 'Don Bosco School (CBSE)' [U-Dise No. 29130128718] at "Khatha No.6605, P.B.No.64 and NH-4 Road, Kelagote, Chitradurga City - 577 501".

Sir,

The Head Master,
The Chitradurga Don Bosco Society,
Don Bosco School (CBSE),
P.B.No.64 N.H. 4 Road,
Next to Basaveshwara Hospital,
Kelagote, Chitradurga City - 577 501.

To,

ANNEXURE-2.

C.No: 11/FSCC(FSR/25/2025)/RFO/DR/2025. Date. 28/11/2025.

Old P.B. Road, Davanagere - 577 003.

Office of the Regional Fire Officer,
Karnataka State Fire and Emergency services,
Davanagere Fire Station Premises,



Tel: 08192-254100
E-mail: rfovg101@gmail.com

Subject to proper maintenance of fire fighting installations in good working conditions and arrange for 40% of staffs/employees should be trained in basic fire fighting within 03 months from the date of issue of this certificate.

In case the fire prevention and fire fighting measures installed as per the recommendation of the department are not maintained in good working condition, if the evacuation measures are not properly followed and if any additional construction work is taken up in the building/premises, the 'Fire Safety Compliance Certificate' deemed to be cancelled and necessary legal action will be initiated against the Management and also separate N.O.C. has to be obtained from the department for the storage of chemicals, solvents, Petroleum products, LPG and etc. in the premises/building.

This 'Fire Safety Compliance Certificate' issued to 'The Chitradurga Don Bosco society, Don Bosco School (CBSE) [U- Dise No. 29130128718].; low-rise already constructed building situated at "Khattha No.6605, P.B.No.64 and NH-4 Road, Kelagote, Chitradurga City--577 501", and it's valid for One (01) year from the date of issue and it is renewable without fail.

Yours faithfully,

Regional Fire Officer,
Karnataka Fire and Emergency Services
Davanagere Range, Davanagere-03

- 1) With respectfully, The Director General of Police and Director General, Karnataka Fire and Emergency Services, Bangalore, 560 042.
- 2) Inspecting Officer / District Fire Officer, Chitradurga Fire Station, Chitradurga.

Copy to :-